

eCopy ScanStation Supported Device List

For Canon TWAIN Supported Devices

The following Canon TWAIN-supported devices are supported by eCopy ShareScan v4.35 for ScanStation:

imageRUNNER Devices	Color imageRUNNER Devices
1023iF/1025iF 2200/2800/3300 2220/3320 2230 2270/2870*/3570*/4570* 2830 3025/3030/3035/3045 3230/3225/3235/3245 3530 5000/6000 5020/6020 5050/5055/5065/5075 5070**/ 5570**/6570** 7086/7095/7105 7200/8500/105 8070/9070/105+	C1022 C4080/ C4580/ C5180/C5185 C3080/C3480 C2380/C3580 C2550 C2620/ C3220 C2880/3380 C3100 C3170 C3200 C5058/C5068 C5800/C6800 C5870/C6870 C5880/C6880
imagePRESS Devices	imageRUNNER ADVANCE Devices
C1 1110/1125/1135 CLC4040/CLC5151	2020 / 2030 - 2020i / 2030i C5030/C5035/C5045/C5051 6075/6065/6055 C7055/C7065 8105/8095/8085 C9065 PRO / C9075 PRO

Not available in US

*Devices are not supported by the ScanStation when used with a Canon B2 or B2 v2 Security Kit

** Devices are not supported the ScanStation when used with a Canon B3 Security Kit

Note: Please note the following configurations are not supported by eCopy ScanStation

VRS TWAIN is not supported by ScanStation

EFI Fiery TWAIN is not supported by ScanStation

Updated 15-NOV-2010